

EAST Search History

EAST Search History (Prior Art)

| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|-------|------|---|-----------------|------------------|---------|---------------------|
| S1 | 2322 | (717/168-178).ccls. and (@ad<"20031104" or @prad<"20031104" or @lad<"20031104") | US-PGPUB; USPAT | ADJ | ON | 2006/10/25 11:32 |
| S2 | 0 | S1 and (software same installation same upgrade same USB) | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 08:50 |
| S3 | 179 | S1 and (software same installation same upgrade) | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 08:52 |
| S4 | 24 | S3 and usb | US-PGPUB; USPAT | ADJ | ON | 2006/10/19 10:55 |
| S5 | 1 | S3 and usb and download and history | US-PGPUB; USPAT | ADJ | ON | 2006/10/19 10:55 |
| S6 | 0 | S3 and (open port) and processor | US-PGPUB; USPAT | ADJ | ON | 2006/10/19 11:09 |
| S7 | 0 | S3 and (open port) | US-PGPUB; USPAT | ADJ | ON | 2006/10/19 11:09 |
| S8 | 0 | S3 and (open near1 port) | US-PGPUB; USPAT | ADJ | ON | 2006/10/19 11:09 |
| S9 | 48 | S3 and port | US-PGPUB; USPAT | ADJ | ON | 2006/10/19 11:10 |

| | | | | | | |
|-----|------|---|--------------------|-----|-----|---------------------|
| S10 | 24 | S3 and usb | US-PGPUB; USPAT | ADJ | ON | 2006/10/19 13:20 |
| S11 | 0 | "09120594" | US-PGPUB; USPAT | ADJ | ON | 2006/10/19 13:20 |
| S12 | 1 | ("6282469").PN. | US-PGPUB; USPAT | OR | OFF | 2006/10/19 13:24 |
| S13 | 29 | "5916287" | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 08:43 |
| S14 | 10 | "5760938" | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 08:43 |
| S15 | 2327 | (717/168-178).ccls. and (@ad<"20031104" or @prad<"20031104" or @lad<"20031104") | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 08:50 |
| S16 | 0 | S15 and (software same installation same upgrade same USB) and (vehicle or automobile) | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 08:51 |
| S17 | 0 | S15 and (software same installation same upgrade same USB) and (vehicle or automobile or automotive) | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 08:52 |
| S18 | 0 | S15 and (software same installation same upgrade same USB) | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 08:52 |

| | | | | | | |
|-----|----|---|-----------------|-----|----|------------------|
| S19 | 6 | S15 and (software same installation same upgrade) and (car or automobile or automotive) | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 09:47 |
| S20 | 56 | S15 and (software same installation same upgrade) and flash | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 09:57 |
| S21 | 0 | S15 and (software same installation same upgrade) and (portable flash) | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 09:47 |
| S22 | 0 | S15 and (software same installation same upgrade) and (flash same USB) | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 09:51 |
| S23 | 36 | S15 and (software same installation same upgrade) and portable | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 09:57 |
| S24 | 16 | S15 and (software same installation same upgrade) and portable and flash | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 09:58 |
| S25 | 0 | S15 and (software same installation same upgrade) and portable near2 flash | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 09:58 |
| S26 | 5 | S15 and (software same installation same upgrade) and portable same flash | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 11:18 |
| S27 | 17 | S15 and (software same installation same upgrade) and removable same flash | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 11:20 |

| | | | | | | |
|-----|---------|--|-----------------|-----|----|---------------------|
| S28 | 1 | S15 and (software same installation same upgrade) and removable near3 flash | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 13:32 |
| S29 | 1 | "10710143" | US-PGPUB; USPAT | ADJ | ON | 2006/10/24 13:33 |
| S30 | 1 | "20050097541" | US-PGPUB; USPAT | ADJ | ON | 2006/10/25 11:31 |
| S31 | 108936 | "L1" | US-PGPUB; USPAT | ADJ | ON | 2006/10/25 11:32 |
| S32 | 2327 | (717/168-178).ccls. and (@ad<"20031104" or @prad<"20031104" or @rlad<"20031104") | US-PGPUB; USPAT | ADJ | ON | 2006/10/25 13:21 |
| S33 | 2327 | S32 | US-PGPUB; USPAT | ADJ | ON | 2006/10/25 11:32 |
| S34 | 0 | S32 and (usb same (portable or removable) near1 flash near3 card) | US-PGPUB; USPAT | ADJ | ON | 2006/10/25 11:34 |
| S35 | 4 | S32 and (usb same (portable or removable) near3 card) | US-PGPUB; USPAT | ADJ | ON | 2006/10/25 11:34 |
| S36 | 4737224 | (@ad<"20031104" or @prad<"20031104" or @rlad<"20031104") | US-PGPUB; USPAT | ADJ | ON | 2006/10/25 13:21 |
| S37 | 380 | S36 and (removable or portable) same USB same flash same card | US-PGPUB; USPAT | ADJ | ON | 2006/10/25 13:22 |
| S38 | 9 | S37 and (software near1 installation) | US-PGPUB; USPAT | ADJ | ON | 2006/10/25 13:22 |

| | | | | | | |
|-----|-----|--|---|-----|-----|---------------------|
| S39 | 0 | 20050102665a1 | US-PGPUB; USPAT | ADJ | ON | 2006/10/27 13:45 |
| S40 | 0 | ("20050102665a1").PN. | US-PGPUB; USPAT | OR | OFF | 2006/10/27 13:45 |
| S41 | 1 | ("20050102665").PN. | US-PGPUB; USPAT | OR | OFF | 2006/10/27 14:28 |
| S42 | 1 | ("20050102666").PN. | US-PGPUB; USPAT | OR | OFF | 2006/10/27 14:28 |
| S44 | 421 | (multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/01/26 22:01 |
| S45 | 28 | S44 and diagnostic and port \$1 and USB and software | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/01/26 22:20 |
| S46 | 1 | "20030163587".PN. | US-PGPUB | ADJ | ON | 2008/01/26 22:08 |
| S47 | 1 | "20020035429".PN. | US-PGPUB | ADJ | ON | 2008/01/26 22:08 |
| S48 | 1 | "6882712".PN. | USPAT; USOCR | ADJ | ON | 2008/01/26 22:09 |

| | | | | | | |
|-----|---|---------------------|---|----|-----|---------------------|
| S49 | 2 | ("6687587").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/01/26 22:21 |
| S50 | 2 | ("6370449").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/01/26 22:23 |
| S51 | 2 | ("20030163587").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/01/26 22:34 |
| S52 | 2 | ("6832141").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/01/26 22:40 |

| | | | | | | |
|-----|---|---------------------|---|----|-----|---------------------|
| S53 | 2 | ("6978198").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/01/26 22:48 |
| S54 | 2 | ("7272475").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/01/26 22:44 |
| S55 | 2 | ("20060271255").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/01/26 22:57 |
| S56 | 2 | ("20060271255").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/01/27 14:31 |

| | | | | | | |
|-----|---|-------------------|---|-----|-----|---------------------|
| S57 | 2 | ("6978198").PN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/01/27 14:31 |
| S58 | 1 | "20030163587".PN. | US-PGPUB | ADJ | ON | 2008/01/27 14:32 |
| S59 | 1 | "20020035429".PN. | US-PGPUB | ADJ | ON | 2008/01/27 14:39 |
| S60 | 2 | ("7272475").PN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/01/27 14:40 |
| S61 | 2 | ("6978198").PN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/01/27 14:40 |
| S62 | 1 | "20030163587".PN. | US-PGPUB | ADJ | ON | 2008/01/27 14:40 |
| S63 | 1 | "20030163587".PN. | US-PGPUB | ADJ | ON | 2008/01/27 14:41 |

| | | | | | | |
|-----|-----|--|---|-----|-----|---------------------|
| S64 | 134 | (automotive or vehicle) same (usb near3 device) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/01/30 08:48 |
| S65 | 4 | (automotive or vehicle) same (usb near3 device) same update\$1 | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/01/30 08:52 |
| S66 | 2 | ("6807469").PN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/01/30 08:53 |
| S67 | 4 | (Holland-Steven-W\$.IN.) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/10/26 10:06 |

| | | | | | | |
|-----|----|---|---|-----|----|---------------------|
| S68 | 1 | (Holland-Steven-W\$IN.) and USB | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/10/26 10:07 |
| S69 | 69 | (vehicle software) same update \$3 | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/10/26 10:14 |
| S70 | 0 | (vehicle software) same update \$3 same USB | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/10/26 10:14 |
| S71 | 4 | ((vehicle software) same update\$3) and USB | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/10/26 10:15 |

| | | | | | | |
|-----|---|--|---|-----|-----|---------------------|
| S72 | 5 | ((vehicle or car or automobile) software) same update\$3) and USB | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/10/26 10:19 |
| S73 | 3 | ((vehicle or car or automobile) software) same update\$3) and USB and diagnostic | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/10/26 10:21 |
| S74 | 2 | ("20030060953").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/10/26 10:29 |
| S75 | 4 | (Holland-Steven-W\$.IN.) | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/11/10 17:13 |

| | | | | | | |
|-----|------|--|---|-----|-----|---------------------|
| S76 | 2 | ("20070050105").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/11/10 17:17 |
| S77 | 7939 | vehicle with (software or driver\$1) with install\$\$5 | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/11/11 15:46 |
| S78 | 327 | vehicle with (software or driver\$1) with install\$\$5 with (status or result\$3) | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/11/11 15:47 |
| S79 | 81 | (vehicle near1 (software or driver\$1)) with install\$\$5 with (status or result\$3) | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/11/11 15:47 |

| | | | | | | |
|-----|----|--|---|-----|----|---------------------|
| S80 | 22 | ((vehicle near1 (software or driver\$1)) near3 install\$\$5) with (status or result\$3) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/11/11 15:48 |
| S81 | 0 | ((vehicle near1 (software or firmware\$1)) near3 install\$ \$5) with (status or result\$3) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/11/11 15:51 |
| S82 | 0 | ((vehicle near1 (software or firmware\$1)) wiht install\$\$5) with (status or result\$3) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/11/11 15:51 |
| S83 | 0 | ((vehicle with (software or firmware\$1)) wiht install\$\$5) with (status or result\$3) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/11/11 15:51 |

| | | | | | | |
|-----|----|--|---|-----|----|---------------------|
| S84 | 0 | ((vehicle with (software or firmware\$1)) wiht install\$\$5) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/11/11 15:54 |
| S85 | 3 | (Knight-Alexander-N\$.IN.) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2008/11/11 15:56 |
| S86 | 10 | (vehicle software) same install \$5 same updat\$3 | US-PGPUB; USPAT | ADJ | ON | 2008/11/13 15:03 |
| S87 | 10 | (vehicle software) same install \$5 same (result or status) | US-PGPUB; USPAT | ADJ | ON | 2008/11/13 15:08 |
| S88 | 7 | (vehicle software) same install \$5 same upgrad\$3 | US-PGPUB; USPAT | ADJ | ON | 2008/11/13 15:12 |
| S89 | 0 | (automobile software) same install\$5 same upgrad\$3 | US-PGPUB; USPAT | ADJ | ON | 2008/11/13 15:12 |
| S90 | 0 | (car software) same install\$5 same upgrad\$3 | US-PGPUB; USPAT | ADJ | ON | 2008/11/13 15:12 |
| S91 | 7 | (vehicle software) same install \$5 same upgrad\$3 | US-PGPUB; USPAT | ADJ | ON | 2008/11/13 15:13 |

| | | | | | | |
|-----|----|---|---|-----|-----|---------------------|
| S92 | 2 | ("6978198").PN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2008/11/13 15:14 |
| S93 | 22 | (multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad \$3)) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 09:38 |
| S94 | 22 | (multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad \$3)) and bus\$2 | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 09:42 |
| S95 | 22 | (multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad \$3)) and bus\$2 and interfac \$3 | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 09:43 |

| | | | | | | |
|-----|----|---|--|-----|----|------------------|
| S96 | 22 | (multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 09:43 |
| S97 | 17 | (multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 and diagnostic | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 09:45 |
| S98 | 20 | (multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3 or install\$5)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 and diagnostic | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 09:46 |

| | | | | | | |
|------|----|--|---|-----|-----|---------------------|
| S99 | 14 | (multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3 or install\$5)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 and (diagnostic same (result \$1 or report(\$3))) | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 09:49 |
| S100 | 2 | ("6687587").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/05/03 09:54 |
| S101 | 2 | ("20030120395").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/05/03 09:55 |
| S102 | 2 | ("6370449").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/05/03 09:57 |

| | | | | | | |
|------|----|--|---|-----|----|---------------------|
| S103 | 13 | (multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3 or install\$5)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 and (diagnostic same (result\$1 or report\$3)) and transfer\$4 | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 10:02 |
| S104 | 13 | (multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3 or install\$5)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 and (diagnostic\$1 same (result\$1 or report\$3)) and transfer\$4 | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 10:05 |
| S105 | 13 | (multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3 or install\$5)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 and (diagnostic\$1 same (result\$1 or report\$3)) and transfer\$4 and diagnostic\$1 | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 10:07 |

| | | | | | | |
|------|-----|---|---|-----|-----|---------------------|
| S106 | 6 | (multiple near3 processor\$1) same (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3 or install\$5)) and bus\$2 and interfac\$3 and (software or firmware) and processor\$1 and (diagnostic\$1 same (result\$1 or report\$3)) and transfer\$4 and diagnostic\$1 and USB\$1 | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 10:08 |
| S107 | 2 | ("6687587").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/05/03 11:37 |
| S108 | 2 | ("20030120395").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/05/03 11:38 |
| S109 | 118 | (multiple near3 processor\$1) and (automobile\$1 or vehicle\$1) and ((software or firmware) (updat\$3 or upgrad\$3)) and diagnostic\$1 | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 12:02 |

| | | | | | | |
|------|-----|---|---|-----|-----|---------------------|
| S110 | 55 | (multiple near3 processor\$1) and (automobile\$1 or vehicle \$1) and (((software or firmware) near2 (updat\$3 or upgrad\$3)) same diagnostic \$1) | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 12:03 |
| S111 | 2 | ("6978198").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/05/03 12:39 |
| S112 | 2 | ("5794164").PN. | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/05/03 12:42 |
| S113 | 155 | ((multiple near3 processor\$1) same (automobile\$1 or car\$1 or vehicle\$1)) and ((software or firmware) near2 (updat\$3 or upgrad\$3 or install\$5)) | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 12:54 |

| | | | | | | |
|------|----|--|---|-----|-----|---------------------|
| S114 | 5 | ((multiple near3 processor\$1) same (automobile\$1 or car\$1 or vehicle\$1)) and ((software or firmware) near2 (updat\$3 or upgrad\$3 or install\$5)) and (open architecture\$1) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 12:54 |
| S115 | 10 | ((multiple near3 processor\$1) same (automobile\$1 or vehicle\$1)) and ((software or firmware) near2 (updat\$3 or upgrad\$3 or install\$5)) and (open interface\$1) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/05/03 12:55 |
| S116 | 5 | Shi-Jianying.IN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 10:32 |
| S117 | 2 | ("5426585").PN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/09/30 10:36 |

| | | | | | | |
|------|-----|---|---|-----|----|---------------------|
| S118 | 882 | ((vehicle near3 software) same (install\$5 or updat\$3)) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 10:49 |
| S119 | 66 | ((vehicle near3 software) same (install\$5 or updat\$3) same processors) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 10:49 |
| S120 | 2 | ((vehicle near3 software) same USB same (install\$5 or updat\$3) same processors) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 10:49 |
| S121 | 12 | ((vehicle near3 software) same (install\$5 or updat\$3) same processors) and USB | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 10:50 |

| | | | | | | |
|------|----|--|--|-----|----|---------------------|
| S122 | 12 | ((vehicle near3 software) same (install\$5 or updat\$3) same processors) and USB and software | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 11:04 |
| S123 | 12 | ((vehicle near3 software) same (install\$5 or updat\$3) same processors) and USB and software and (status or result or diagnostic) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 11:05 |
| S124 | 66 | ((vehicle near3 software) same (install\$5 or updat\$3) same processors) and software | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 14:42 |
| S125 | 82 | ((vehicle near3 software) same (install\$5 or updat\$3 or load\$2) same processors) and software | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 15:11 |

| | | | | | | |
|------|----|--|---|-----|----|---------------------|
| S126 | 72 | ((vehicle near3 software) same (install\$5 or updat\$3 or load\$2) same processors) and software and type\$1 | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 15:12 |
| S127 | 30 | ((vehicle near3 software) same (install\$5 or updat\$3 or load\$2) same processors) and software and ((identif\$5 or determin\$3) near2 type\$1) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 15:13 |
| S128 | 0 | Knight-Alexander.IN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 15:21 |
| S129 | 3 | Knight-Alexander-N\$.IN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 15:22 |

| | | | | | | |
|------|------|--|--|-----|----|---------------------|
| S130 | 1021 | (vehicle near3 software) same (install\$5 or updat\$3 or load\$2) and (software or firmware or driver\$1) | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 17:40 |
| S131 | 1021 | (vehicle near3 software) same (install\$5 or updat\$3 or load\$2) same (software or firmware or driver\$1) | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 17:40 |
| S132 | 124 | (vehicle software) same (install\$5 or updat\$3 or load\$2) same (software or firmware or driver\$1) | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 17:40 |
| S133 | 11 | (vehicle software) same processors same (install\$5 or updat\$3 or load\$2) same (software or firmware or driver\$1) | US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 17:40 |

| | | | | | | |
|------|---|--|---|-----|-----|---------------------|
| S134 | 6 | (vehicle software) same processors same (install\$5 or updat\$3 or load\$2) same (software or firmware or driver\$1) and software and load\$3 | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/09/30 17:45 |
| S135 | 2 | ("6978198").PN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/11/10 17:01 |
| S136 | 2 | ("20030163587").PN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/11/10 17:05 |
| S137 | 2 | ("6832141").PN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/11/10 17:43 |

| | | | | | | |
|------|-----|---|---|-----|-----|---------------------|
| S138 | 173 | (vehicle or automobile) near3 (software updat\$3) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/11/10 17:46 |
| S139 | 4 | ((vehicle or automobile) near3 (software updat\$3)) same status | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/11/10 17:47 |
| S140 | 2 | ("20020035429").PN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/11/10 17:49 |
| S141 | 2 | ("20040078119").PN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/11/10 17:52 |

| | | | | | | |
|------|-----|--|---|-----|-----|---------------------|
| S142 | 173 | (vehicle or automobile) near3 (software updat\$3) | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | ADJ | ON | 2009/11/10 22:23 |
| S143 | 2 | ("20080104583").PN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/11/10 22:24 |
| S144 | 8 | ("7506309").PN. | US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2009/11/10 23:26 |

11/20/2009 4:57:31 PM

C:\Documents and Settings\bwang\My Documents\EAST\Workspaces\2006\2006-Q4
\10701143.wsp